

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

10 Ulveston Rd 2

Certificate No: 976785

Engineers Details						Insta	Installation Details						Client Details							
Trading Title		Dean Turner plumbing And heating engineer Ltd						allation	Andrew Read					Client	7 1101	ew Read				
Address		Tenterfield						ress	10 Ulver	erston Rd				Address	IN UI	10 Ulverston Rd				
		Hallthwaites							Lindal						Linda	Lindal				
		Post Code: LA185HP							Post Code: LA120LP								Post Coc	le: LA120	LP	
Gas Safe No:		177975 Telephone No: 07515774216					Tele	Telephone No:				Telephone No:								
Appliance Details									Inspec	tion Det	ails				L					
	Locatio	Location .		псе Туре	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) (VD - Veuel Impedent Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Visual Condition Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathroom C	Bathroom Cupboard		oi Boiler	Main	25 Eco Elite	9.2	34	RS	YES	0.0003	YES	19.6 mbar	YES	YES	YES	PASS	NO	YES	
2																				
3																				
4																				
5																				
Faults/Notes							Remedial Work Taken									Warnii	Warning Notice Fixed			
1	1 unable to gain access to the gas meter for tightness test																	NO		
2	1																			
3	1																			
4																				
5																				
Emergency Control Valve Accessible: Yes Gas Tightness Satisfactory: NA									Signatures Gas ID Number:   Report Issued By: Gas ID Number:											
Ga	s Installation	Pipework	< Visual In	spection Sa	atisfactory:		Name: Dean Turner Signed:					d:	0: Sanuel	Tue-30-	Tue-30-Jan-2024					
Nu	mber of Appli	ances Te	ested:	1	Equipotential E	Bonding: Yes		port Received By:												
NEXT INSPECTION DUE ON OR BEFORE: Thu-30-Jan-2025 Installation Pass: No							· –	ot Presen	-		Signe	Signed:				Tue-30-Jan-2024				
CO Alarm fitted & working? NO Smoke alarm fitted & working? YES								This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk												

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.